



Perth Amboy Public Schools

Administrative Headquarters Building
178 Barracks Street
Perth Amboy, NJ 08861
(732) 376-6200

Michael LoBrace
Business Administrator
Board Secretary



June 12, 2023

DUAL LANGUAGE SCHOOL
630 Amboy Ave
Edison, NJ 08837

Dear Dual Language School Community:

Our school system is committed to protecting student, teacher, and staff health. To protect our community and be in compliance with the Department of Education regulations, the district tested our schools' drinking water for lead.

In accordance with the Department of Education regulations, Dual Language School will implement immediate remedial measures for any drinking water outlet with a result greater than the action level of 15 µg/l (parts per billion [ppb]). This includes turning off the outlet unless it is determined the location must remain on for non-drinking purposes. In these cases, a "DO NOT DRINK – SAFE FOR HANDWASHING ONLY" sign will be posted.

Testing Results

Following instructions given in technical guidance developed by the New Jersey Department of Environmental Protection, we completed a plumbing profile for each of the buildings within the district. Through this effort, we identified and tested all drinking water and food preparation outlets. Of the 13 samples taken, all but 1 tested below the lead action level established by the US Environmental Protection Agency for lead in drinking water (15 µg/l [ppb]).

The table below identifies the drinking water outlets that tested above the 15 µg/l for lead, the actual lead level, and what temporary remedial action the Perth Amboy School District has taken to reduce the levels of lead at these locations.

Sample Location	First Draw Result in µg/l (ppb)	Remedial Action
2 OLPG-WC-HALLGL Hall near Gym left water cooler	18.6 New 228	Disconnected outlet. Location mark "Out of Order". Re-Tested in July 2022 test result: 228

Health Effects of Lead

High levels of lead in drinking water can cause health problems. Lead is most dangerous for pregnant women, infants, and children under 6 years of age. It can cause damage to the brain and kidneys and can interfere with the production of red blood cells that carry oxygen to all parts of your body. Exposure to high levels of lead during pregnancy contributes to low birth weight and developmental delays in infants. In young children, lead exposure can lower IQ levels, affect hearing, reduce attention span, and hurt school performance. At *very* high levels, lead can even cause brain damage. Adults with kidney problems and high blood pressure can be affected by low levels of lead more than healthy adults.



Perth Amboy Public Schools

Administrative Headquarters Building
178 Barracks Street
Perth Amboy, NJ 08861
(732) 376-6200

How Lead Enters our Water

Lead is unusual among drinking water contaminants in that it seldom occurs naturally in water supplies like groundwater, rivers and lakes. Lead enters drinking water primarily as a result of the corrosion, or wearing away, of materials containing lead in the water distribution system and in building plumbing. These materials include lead-based solder used to join copper pipe, brass, and chrome-plated brass faucets. In 1986, Congress banned the use of lead solder containing greater than 0.2% lead, and restricted the lead content of faucets, pipes and other plumbing materials. However, even the lead in plumbing materials meeting these new requirements is subject to corrosion. When water stands in lead pipes or plumbing systems containing lead for several hours or more, the lead may dissolve into the drinking water. This means the first water drawn from the tap in the morning *may* contain fairly high levels of lead.

Lead in Drinking Water

Lead in drinking water, although rarely the sole cause of lead poisoning can significantly increase a person's total lead exposure, particularly the exposure of children under the age of 6. EPA estimates that drinking water can make up 20% or more of a person's total exposure to lead.

For More Information

For more information about water quality in our schools, contact Carmen Southward, District Director of Operations, at (732) 376-6200.

For more information on reducing lead exposure around your home and the health effects of lead, visit EPA's Web site at **www.epa.gov/lead**, call the National Lead Information Center at 800-424-LEAD, or contact your health care provider.

If you are concerned about lead exposure at this facility or in your home, you may want to ask your health care providers about testing children to determine levels of lead in their blood.

Sincerely,

A handwritten signature in blue ink, appearing to read "LoBrace", is written over the word "Sincerely,".

Michael LoBrace
Business Administrator/Board Secretary
Perth Amboy Board of Education



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone: (856) 303-2500 Fax: (856) 858-4571 Email: EnvChemistry2@emsl.com

Attn:

Tim Popp
TTI Environmental Inc.
1253 North Church Street
Moorestown, NJ 08057

1/19/2022

Phone: (856) 840-8800
Fax: (856) 840-8815

The following analytical report covers the analysis performed on samples submitted to EMSL Analytical, Inc. on 1/5/2022. The results are tabulated on the attached data pages for the following client designated project:

21-211 Our Lady of Peace (Gymnasium)

The reference number for these samples is EMSL Order #012200591. Please use this reference when calling about these samples. If you have any questions, please do not hesitate to contact me at (856) 303-2500.

Approved By:

Phillip Worby, Environmental Chemistry
Laboratory Director



The test results contained within this report meet the requirements of NELAP and/or the specific certification program that is applicable, unless otherwise noted.
NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, CA ELAP 1877

The samples associated with this report were received in good condition unless otherwise noted. This report relates only to those items tested as received by the laboratory. The QC data associated with the sample results meet the recovery and precision requirements established by the NELAP, unless specifically indicated. All results for soil samples are reported on a dry weight basis, unless otherwise noted. This report may not be reproduced except in full and without written approval by EMSL Analytical, Inc.

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012200591

CustomerID: TTIE54

CustomerPO: 034117

ProjectID:

Attn: **Tim Popp**
TTI Environmental Inc.
1253 North Church Street
Moorestown, NJ 08057

Phone: (856) 840-8800
Fax: (856) 840-8815
Received: 1/5/2022 01:45 PM

Project: 21-211 Our Lady of Peace (Gymnasium)

Analytical Results

Client Sample Description 1 OLPG-WC-HALLGR		Collected: 1/5/2022 10:30:00 AM		Lab ID: 012200591-0001	
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.16	1.00 µg/L	1/17/2022 KB	1/18/2022 KB 02:26
Client Sample Description 2 OLPG-WC-HALLGL		Collected: 1/5/2022 10:30:00 AM		Lab ID: 012200591-0002	
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	18.6	1.00 µg/L	1/17/2022 KB	1/18/2022 KB 02:27
Client Sample Description 5 OLPG-WC-HALLBL		Collected: 1/5/2022 10:31:00 AM		Lab ID: 012200591-0003	
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	1.28	1.00 µg/L	1/17/2022 KB	1/18/2022 KB 02:29
Client Sample Description 6 OLPG-WC-HALLBL		Collected: 1/5/2022 10:31:00 AM		Lab ID: 012200591-0004	
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	2.25	1.00 µg/L	1/17/2022 KB	1/18/2022 KB 02:30
Client Sample Description 9 Field Blank		Collected: 1/5/2022		Lab ID: 012200591-0005	
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	1/17/2022 KB	1/18/2022 KB 02:35



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>

EnvChemistry2@emsl.com

EMSL Order:	012200591
CustomerID:	TTIE54
CustomerPO:	034117
ProjectID:	

Definitions:

MDL - method detection limit

J - Result was below the reporting limit, but at or above the MDL

ND - indicates that the analyte was not detected at the reporting limit

RL - Reporting Limit (Analytical)

D - Dilution Sample required a dilution which was used to calculate final results



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone: (856) 303-2500 Fax: (856) 858-4571 Email: EnvChemistry2@emsl.com

Attn:

Tim Popp
TTI Environmental Inc.
1253 North Church Street
Moorestown, NJ 08057

1/18/2022

Phone: (856) 840-8800
Fax: (856) 840-8815

The following analytical report covers the analysis performed on samples submitted to EMSL Analytical, Inc. on 1/5/2022. The results are tabulated on the attached data pages for the following client designated project:

21-211/Our Lady of Peace (School)

The reference number for these samples is EMSL Order #012200559. Please use this reference when calling about these samples. If you have any questions, please do not hesitate to contact me at (856) 303-2500.

Approved By:

Phillip Worby, Environmental Chemistry
Laboratory Director



The test results contained within this report meet the requirements of NELAP and/or the specific certification program that is applicable, unless otherwise noted.

NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, CA ELAP 1877

The samples associated with this report were received in good condition unless otherwise noted. This report relates only to those items tested as received by the laboratory. The QC data associated with the sample results meet the recovery and precision requirements established by the NELAP, unless specifically indicated. All results for soil samples are reported on a dry weight basis, unless otherwise noted. This report may not be reproduced except in full and without written approval by EMSL Analytical, Inc.

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012200559

CustomerID: TTIE54

CustomerPO: 034117

ProjectID:

Attn: **Tim Popp**
TTI Environmental Inc.
1253 North Church Street
Moorestown, NJ 08057

Phone: (856) 840-8800
 Fax: (856) 840-8815
 Received: 1/5/2022 01:45 PM

Project: 21-211/Our Lady of Peace (School)

Analytical Results

Client Sample Description 2 OLP-DW-CUSTR Outside Office (Right)		Collected: 1/5/2022 10:07:00 AM		Lab ID: 012200559-0001	
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	1.82	1.00 µg/L	1/14/2022 KB	1/14/2022 KB 23:44
Client Sample Description 3 OLP-WC-105 Hall at Room 105		Collected: 1/5/2022 10:06:00 AM		Lab ID: 012200559-0002	
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	1/14/2022 KB	1/14/2022 KB 23:46
Client Sample Description 4 OLP-WC-2FL 2nd Floor at Girl's Bathroom		Collected: 1/5/2022 10:17:00 AM		Lab ID: 012200559-0003	
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	1/14/2022 KB	1/14/2022 KB 23:47
Client Sample Description 5 OLP-SF-NURSEO Nurse Office		Collected: 1/5/2022 10:18:00 AM		Lab ID: 012200559-0004	
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.19	1.00 µg/L	1/14/2022 KB	1/14/2022 KB 23:49
Client Sample Description 8 OLP-SF-K2 Kitchen Double Tub		Collected: 1/5/2022 10:09:00 AM		Lab ID: 012200559-0005	
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	1/14/2022 KB	1/14/2022 KB 23:50

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012200559

CustomerID: TTIE54

CustomerPO: 034117

ProjectID:

Attn: **Tim Popp**
TTI Environmental Inc.
1253 North Church Street
Moorestown, NJ 08057

Phone: (856) 840-8800
 Fax: (856) 840-8815
 Received: 1/5/2022 01:45 PM

Project: 21-211/Our Lady of Peace (School)

Analytical Results

Client Sample Description	9 OLP-WC-CAFE Café near Kitchen	Collected:	1/5/2022 10:11:00 AM	Lab ID:	012200559-0006
----------------------------------	------------------------------------	-------------------	-------------------------	----------------	----------------

<i>Method</i>	<i>Parameter</i>	<i>Result</i>	<i>RL Units</i>	<i>Prep Date & Analyst</i>	<i>Analysis Date & Analyst</i>
METALS					
200.8	Lead	ND	1.00 µg/L	1/14/2022 KB	1/14/2022 KB 23:52

Client Sample Description	11 OLP-SF-NURSE 2 Nurse Exam Room	Collected:	1/5/2022 10:20:00 AM	Lab ID:	012200559-0007
----------------------------------	--------------------------------------	-------------------	-------------------------	----------------	----------------

<i>Method</i>	<i>Parameter</i>	<i>Result</i>	<i>RL Units</i>	<i>Prep Date & Analyst</i>	<i>Analysis Date & Analyst</i>
METALS					
200.8	Lead	6.32	1.00 µg/L	1/14/2022 KB	1/14/2022 KB 23:53

Client Sample Description	12 Field Blank Blank	Collected:	1/5/2022	Lab ID:	012200559-0008
----------------------------------	-------------------------	-------------------	----------	----------------	----------------

<i>Method</i>	<i>Parameter</i>	<i>Result</i>	<i>RL Units</i>	<i>Prep Date & Analyst</i>	<i>Analysis Date & Analyst</i>
METALS					
200.8	Lead	ND	1.00 µg/L	1/14/2022 KB	1/14/2022 KB 23:55

Definitions:

MDL - method detection limit

J - Result was below the reporting limit, but at or above the MDL

ND - indicates that the analyte was not detected at the reporting limit

RL - Reporting Limit (Analytical)

D - Dilution Sample required a dilution which was used to calculate final results